FOLLOWING DATA TO BE ANSWERED BY INSPECTOR MIG AND SIGNED WHEN RETURNED

N? 2354

	TINITY 1900 ST
Date Inspected OC1-4	If so how and location from first manhole down stream
House No. クタケ	Distance from first manhole
Size of pipe used	down stream to ditch at — curb line and depth
Was lateral at curb? No	- 1 011.44-
Was attached to main yes	Name of Contractor Wittman
Show by diagram relation of lateral	(A)
clance with Ordinance No. 23.3, unly (Fight: Serve	694 ft- from Man Hole to Y 9 ft-D Main Sever
Signed A. T. Boyd	Gity Walanch - ave Filed at Engineer's Office 007 6 1926
Inspector for Remarks Lateral Comm	ected to Main 54 ft from Man Hole

HOTDERS MI THE CHERT WANT ASSET ATAG DESWOLED?

CHARLITER MEANY CHARLE OF THE DIRECTOR OF PUBLIC SERVICE

DEDD MICH. (DO. CDA.D. CENTER)

Nº 235	4		IU IAF	SEW EN	.
	most nelised bus Lugara nyob eje	voi e il Jasa isti	illon, O.,	17.70	1
	piešiuju jani moj	Mass	sillon, O.,	CV , Teasing	
	Julio Sinis	Mit	t	fee of \$	ا ل ســ
for which permiss	ion is granted	ing Ad	mada	yir beliadin ed markab victor	
to tap	und any	sewer, on	the -	month	
. M	abol	Ave	, the premises be	ing Lot. No.	12
		St.			

House No. 125 Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Withau