

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 2376

3-46 ✓

Date Inspected Oct 19

If so how and location from
first manhole down stream

House No. 113

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.



6
38 ft Pipe

6 ← Main sewer

Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office OCT 20 1926

Remarks lateral connected to lateral at curb 3 ft from side
line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2376

PERMIT TO TAP SEWER

1:30

Massillon, O., Oct 18th 19

Received of Mr. Early fee of \$ 2.00

for which permission is granted Mr. Early

to tap sanitary sewer, on the east

of W. Cherry Ave., the premises being Lot. No. 1
St.

House No. 113 Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor Early