

Nº 2386

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

THERE WAS NO STOPPER OR SCREEN IN CELLAR DRAIN
AT THIS TIME

DEC. SHERTZER

Date Inspected OCT-22

If so how and location from
first manhole down stream MCZIEGLER AGENCY

House No. 316

Distance from first manhole
down stream to ditch at
curb line and depth 128' WEST OF W. P. L. 35' S.W. - 5' 6"


Size of pipe used 4 in

Was lateral at curb? yes

Name of Contractor Geo. Early

Was attached to main

Show by diagram relation of lateral to wall of building served.



THIS SEWER WAS dug up on
acct. STOPPAGE in lateral at
curb line and at bend about
6' NO. OF CURB, COAL GRAVEL and
CHUNKS OF GRASS TAKEN OUT
Ran rods thru also flushed toilet
MCZIEGLER was there and
SEEMED satisfied it was open.

Signed A. J. Boyd
Inspector for City

Filed at Engineer's Office

OCT 23 1926

Remarks Lateral connected to lateral at curb 24 ft from street
on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2386

PERMIT TO TAP SEWER

Massillon, O.,

Oct 21st

19

Received of

Mr. Sherman

fee of \$2.00

for which permission is granted

Geo. Early

to tap

Sanitary

sewer, on the

North

of

W. Tremont

Ave., the premises being Lot No.

307

St.

1054

House No. 316

Work to be done in accordance with Ordinance No. 2323, duly p

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Geo. Early