

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 2399

Date Inspected Nov 2

If so how and location from
first manhole down stream

House No. New 418

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 4 in

Was lateral at curb? yes

Name of Contractor M E Lembach

Was attached to main

Show by diagram relation of lateral to wall of building served.



60 ft Pipe
8

Main sewer → South

Hamilton Ave

Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office

NOV 3 1926

Remarks Lateral connected to lateral at curb 46 ft from a
line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2399

PERMIT TO TAP SEWER

Massillon, O., Oct 28th 19

Received of W. J. Schuch fee of \$ 2.00

for which permission is granted 2 ft. 6 in. diameter

to tap sanitary sewer, on the east

of Hamilton Ave., the premises being Lot No. 5039
19th ST NW 7375

House No. 418. Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor W. J. Schuch