

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2401

Date Inspected Oct 30

If so how and location from
first manhole down stream

House No. 1613

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor M E Lemfack

Was attached to main

Show by diagram relation of lateral to wall of building served.

House

22 ft Pipe
5



Main Sewer → West

West Fremont St

Signed A. T. Boyd
Inspector for City

Filed at Engineer's Office NOV 2 1926

Remarks Lateral connected to lateral at curb 22 ft from
straight line on Hor

[illegible]

...and the

8100

D SEWER

Massillon, O., Oct 29th

Mr. E. L. ... fee of \$ 2.00

granted 12 E. H. H. H.

sewer on the south

West Island Ave., the premises being Lot. No. 3871
St.

1613. Work to be done in accordance with Ordinance No. 2323, duly passed.

Lundbach