

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

6-19

No. 2402

Date Inspected Nov 3

If so how and location from
first manhole down stream

House No. 1322

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.



Main sewer → South

Cleveland Ave

Signed A T Boyd
Inspector for City

Filed at Engineer's Office NOV 4 1926

Remarks Lateral connected to lateral at curb 28 ft from
line on Ho

RECEIVED DATA TO BE ANSWERED BY INSPECTOR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2402

PERMIT TO TAP SEWER

Massillon, O., Nov 1st 1919

Received of

fee of \$

for which permission is granted

to tap

sewer, on the

of

Ave., the premises being Lot. No. 4195
St. 4195

House No. 1322

Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor