

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

6-19

Nº 2410

Date Inspected 1251

If so how and location from
first manhole down stream

House No. 1303 Rear

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"


252 From M.H. South 7'6" Deep

Was lateral at curb? Yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.



Signed

John E. Hemen
Inspector for City

Filed at Engineer's Office

NOV 12 1926

Remarks

Line in same Ditch as House in Front

8:00

8100
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
SIGNED WHEN RETURNED

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2410

PERMIT TO TAP SEWER

Massillon, O.,

Nov-4-

19

Received of

Mrs Anna Blaza

fee of \$

2.00

for which permission is granted

to tap

Sanitary

sewer, on the

West

of

Cleveland

Ave., the premises being Lot. No.

89

St.

4151

House No.

~~1303~~
1251

Work to be done in accordance with Ordinance No. 2323, duly passed

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Sam Toben