

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

6-19

N^o 2415

Date Inspected Nov 30

If so how and location from
first manhole down stream

House No. 1272

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6"

97 ft. 7 deep


Was lateral at curb? yes

Name of Contractor

Was attached to main yes

J. Hattmann

Show by diagram relation of lateral to wall of building served.



Signed

J. Ehrmer
Inspector for City

Filed at Engineer's Office

DEC 5 1926

Remarks

Following data to be answered by inspector

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2415

PERMIT TO TAP SEWER

Massillon, O.,

Nov 8th 19

Received of

Julius W. Hattmann

fee of \$

2⁰⁰

for which permission is granted

John Truller

to tap

sanitary

sewer, on the

west

of

Cleveland

Ave., the premises being Lot. No. 4516
St. 4358 4184

House No. 1212 Work to be done in accordance with Ordinance No. 2323, duly pa

by the City Council, and Rules of the Department of Public Service.

Name of Contractor

W. Hattmann