FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 2420 AND SIGNED WHEN RETURNED Date Inspected 11/19/26 If so how and location from first manhole down stream. House No. - No house built yet Distance from first manhole Size of pipe used 6" 11.5.P. down stream to ditch at Was lateral at curb? Yeo my de fellock Name of Contractor Was attached to main_____ Show by diagram relation of lateral to wall of building served. yvyser in be done in accordance with Dydmance No. 2323, duly passed by the Chy Cauncil, and Wales at He British of the Printer Comme Signed Geo, C. Phallace Filed at Engineer's Office..... NOV 1 9 1926 Inspector for City political strange of the sevent was 173 Deep a house end both Limbs. Remarks The Lower build protection lot in political to the Audio Kepsentine of Gilty said it was O. (+ e.w.

HOTOGRAFIA DE ANSWERED BY INSPECTOR OF PUBLIC SERVICE

Nº 2420

8:00

PERMIT TO TAP SEWER

anort nonscoi bas wed as		<u> </u>	~ d
st manifole cown stream	Massillon, O.,	Region.	<u>∛</u> 192_
Received of A 2010 Trace 18	ilt.	fee	or 8 200
for which permission is granted	م لم حساس		Vas intere
to tap sew	ver, on the		Las avi
\mathcal{M} . The h_{u} is a factor h_{u}	Ave., Type of Stree		b wil world
the premises being Lot. No. 5016	St. House No.		E16
Work to be done in accordance with Ordinance No		y the City Co	ouncil, and Rule
the Department of Public Service.			
Name of Contractor Junta Lak			benyik

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.