

✓

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

6-19

Nº 2438

Date Inspected Dec 2

If so how and location from
first manhole down stream

House No. 1019

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? yes

Name of Contractor

Dan Robin

Was attached to main

Show by diagram relation of lateral to wall of building served.



1/2
28 ft Pipe
1/2

South ← Main Sewer

bleeland ave

Signed A. T. Boyd

Inspector for City

Filed at Engineer's Office

DEC 3 1926

Remarks

lateral connected to lateral at curb 8 ft from stair
House very low line on Hoe

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2438

PERMIT TO TAP SEWER

Massillon, O.,

Nov. 19th 192

Received of

Sam T. Linn

fee of \$

2⁰⁰

for which permission is granted

Sam T. Linn

to tap

sanitary

sewer, on the

west

of

Cleveland

Ave., Type of Street

ditch

St.

the premises being Lot. No.

4375

4166

House No.

1019

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of the Department of Public Service.

Name of Contractor

Sam T. Linn

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.