FOLLOWING DATA TO BE ANSWERED BY INSPECTOR NO. 2457 AND SIGNED WHEN RETURNED Date Inspected Dec 19 If so how and location from first manhole down stream. House No. New Distance from first manhole down stream to ditch at curb line and depth.

Was attached to main_______ Name of Contra Show by diagram relation of lateral to wall of building served.

Section of the property of the section of the secti

Was lateral at curb? Mls

Name of Contractor & Withman
building served. House

Signed A. H. Boyd

Signed A. G. Boyd

Filed at Engineer's Office.

Remarks Lateral Connected to taleral at curb 33 ft from st

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2457

PERMIT TO TAP SEWER

ssort noisepal with west in it
Received of Julian Hallanning fee of \$ 200
for which permission & granted 9/5, C, D. J.
to tap Sanda Sewer, on the Joseph as 77
Ave., Type of Street
the premises being Lot. No. 3732. House No.
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule
the Department of Public Service. Name of Contractor Name of Contractor
Name of Contractor Problems in the contractor of