FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Tel 19 House No. 13	HOTHERAN first manhole down stream
Size of pipe used de	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb? agled.	
Was attached to main	Name of Contractor & Wildow
Show by diagram relation of lateral	to wall of huilding served.
그들은 이 생물에 들었다면 하는 것이 나가 되었다.	근데 그들의 몇시 마쳤어 하는 쌀으로 가는 이 사고 있는데 말이 아이들은 그 이 모든 이 불을 할
i al Suece	
보는 그는 항상 보통하는 것이 있는 것이다. 1982년 - 1일	
보는 그는 항상 보통하는 것이 있는 것이다. 1982년 - 1일	
cki sere	1 10 /3 4 ft Pife
cki sere	
cki sere	1 10 /3 4 ft Pife
cki sere	South & Main Beyon and
cki sere	1 203/314 ft Paper

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2517 PERMIT TO TAP SEWER

o how shift focusion from	
Received of Modan And South	fee of \$ 2
for which permission is granted	
and the second of the second property of the second	ewer, on the
of Itanh Ih. It.	Ave., Type of Street.
the premises being Lot. No. 2272	House, No/_3
Work to be done in accordance with Ordinance	No. 2323, duly passed by the City Council, and Ru
the Department of Public Service. Name of Contractor	
and the second of the sail of the second	de of building only. Any work inside walls of bu