

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 2530

Date Inspected March 12

If so how and location from
first manhole down stream

House No. 1116

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6 in


Was lateral at curb? No

Name of Contractor

Was attached to main on Y

Show by diagram relation of lateral to wall of building served.

Chas Stroud



Signed A. H. Boyd
Inspector for City

Filed at Engineer's Office

MAR 15 1927

Remarks Lateral connected to Main on Ross St 17 ft from M
H

