FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED  $N^{\circ}$  2547 Date Inspected Mauch 23 If so how and location from first manhole down stream... House No. 221 Distance from first manhole down stream to ditch at Size of pipe used 6 M curb line and depth..... Was lateral at curb? Was attached to main. Show by diagram relation of lateral to wall of building served. art de recorded with Onlineau Mas 1922, duly passed by the Hity Council, and Rolling Inspector for City

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

2547

is subject to Massillon Board of Health Regulations.

If so kow and lecalide from mesternwoh stodasm son Massillon, O.,\_\_\_ for which permission is granted Ave., Type of Street. Duncan ST Sw 16215 House No. the premises being Lot. No. Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rul the Department of Public Service. Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of bu

PERMIT TO TAP SEWER