FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED . 2556 Date Inspected////wr If so how and location from first manhole down stream Distance from first manhole down stream to ditch at Size of pipe used curb line and depth.... Was lateral at curb? Meo Name of Contractor Was attached to main_____ Show by diagram relation of lateral to wall of building served. be done in accordance with Ordinance No. 2323; duly massed by the City Council, and Rules of Filed at Engineer's Office. Inspector for City have goden wind harden to absence have resume there are all INT. it sainte in Massino itensi opinali de minarons. Remarks____

Nº 2556

PERMIT TO TAP SEWER

enesî dedi.	not have wed in i	Massillan O			
Received of Daniel	en autoriale to a Lol	Massillon, O.,		1.54/1.54/2.	
for which permission is granted.	Sent distribution of the sent	- 24d	<u>Lance</u>		
to tap dand air		Ave., Type of Stre	enginisi dis	did	27
the premises being Lot. No.	3013	St. House No			
Work to be done in accordance wi	th Ordinance No.	2323, duly passed	by the City	Council, a	ınd Rul
the Department of Public Service. Name of Contractor	<i></i>				
		The second of the second second second			

NOTE. This permit covers work outside of building only. Any work inside walls of bui is subject to Massillon Board of Health Regulations.