FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Nº 2603 4 - 53Date Inspected Man 3 If so how and location from first manhole down stream. House No. /2 /2 Distance from first manhole. down stream to ditch at Size of pipe used curb line and depth..... Was lateral at curb? Name of Contractor 1 Was attached to main_____ Show by diagram relation of lateral to wall of building served, Andrew Commence of the Commenc daly present by the City Closecol, and Rules of

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2603

PERMIT TO TAP SEWER

	mari nelikasi bus wade Limpus, ippb-efoliuku	Massillon, O.,	may	ر المراجع المر 192.
	of from first from			a interpretation
Received of	Lyshin in Anna Cit	Lange Long.		fee of \$
for which permission is	granted 21.	haran	A contact	te formal to V
to tap	at any	ewer, on the	ili. iningo	Socioni Aran Vi
of 18	1 St. S. E	ligd to list of istals	i fa nonska mi Street	eling viole
13th S	t se No <i>785</i>	St. 2266 House	No	* ***********************************
Work to be done in acc	ordance with Ordinance I	No. 2323, duly pass	ed by the City	Council, and Rule
the Department of Publi	c Service.			
Name of Contractor	1 Downstill	estate production of the second of the secon		. Vibonik
NOTE. This p	bermit covers work outsi Board of Health Regul	de of building only ations.	Any work is	uside walls of buil