

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 2624

19-47

Date Inspected May 20, 27

If so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 6" Pipe?

Was lateral at curb? Yes

Name of Contractor

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



7' Deep

48' of Pipe

7' Deep

Prop. CURB LINE

Geo. C. Wallace

Signed

Wm. H. Maltby

Inspector for City

Filed at Engineer's Office

COLUMBUS ST

Remarks

*Pipe was laid + Ditch 1/2 back filled water pipe laid above Sew.
This pipe was laid without inspector -*

JUN 10 1927

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2624

PERMIT TO TAP SEWER

Massillon, O., May 20th 1922Received of Dan Tobin fee of \$ 2.00for which permission is granted Willis Detorreeto tap Sanitary sewer, on the West?of Columbus Ave., Type of Street Dirt
St.the premises being Lot No. Rt 2 L. 41 House No. New House

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule
the Department of Public Service.

Name of Contractor Dan Tobin

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.