LLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Nº 2647 Date Inspected Jump 29 If so how and location from first manhole down stream House No. 72/ Distance from first manhole down stream to ditch at Size of pipe used. 4 and curb line and depth..... Was lateral at curb? Name of Contractor Diel Was attached to main____ Show by diagram relation of lateral to wall of building served. ance with Orthmane Mr. 2323, duly passed by the City Council, and Rules Es Inspector for City

TOTO E TOTAL OF A OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2647

PERMIT TO TAP SEWER

	so how and lounded from	taka aliku ku ili 100 km ili ⊑aka ku ili k asa il i. K	ne 93 7/ 192,
Received of	Manager on her manager	though	fee of 8 22
for which permission i	Line So, j ornatio G to see		<u>ison de princial de principal de princip</u>
to tap of	Set (1972)	ver, on the nd to the large of treet	Les energes to your
the premises being Lo	No. 1846	St. House No.	72/
Work to be done in a	cordance with Ordinance N	o. 2323, duly passed by th	e City Council, and Rule
the Department of Pul	olic Service.		
in in a single in the single i	to bolici / #	a of huilding only Any	pork inside walls of huil

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.

i in analyti

1.6.5.5.5.4.5

(X5.32) (8.38)