FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 2661 AND SIGNED WHEN RETURNED 1965 Date Inspected Buly 5' If so how and location from first manhole down stream... House No. 735 Distance from first manhole down stream to ditch at Size of pipe used 6 curb line and depth..... Was lateral at curb?

Was attached to main.....

Show by diagram relation of lateral to wall of building served.

e problem being Loc. Me A & other done in nonanting with Ordana Land, duly maked by the Charle concil, and content

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 2661

PERMIT TO TAP SEWER

		rest noderal bas we wood signification	ui us ii Massil Massil	lon, O. Lu	Misson and	() 192
	Received of	Children mon's	are to CA 1 for	v-n d	fee of \$	2 20
	for which permission is	granted L	+ ma	-y a	L ipin Jawidi sa	77
	to tap	Mary	sewer, on th		an Ordensandus Promerandus	
	of <u>Nd-</u>		Ave., 7	Гуре of Street	din	
	the premises being Lot.	No. 19/5		_House No	935	
	Work to be done in ac		ce No. 2323, c	luly passed by the	e City Council, a	and Rule
in the second	the Department of Pub Name of Contractor	lic Service.				

NOTE. This permit covers work outside of building only. Any work inside walls of build is subject to Massillon Board of Health Regulations.