| . Nº 2700 | FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED | | |
|--|--|--|--|
| Date Inspected 4 1113 17 House No. 75 | If so how and location from first manhole down stream | | |
| Size of pipe used 6 222 | Distance from first manhole down stream to ditch at curb line and depth | | |
| Was lateral at curb? Myld. | Name of Contractor 6 Mas 3 Mrs. College Contractor 1 Mas 2 Mrs. College Contractor 1 Mas 2 Mrs. College Colleg | | |
| Was attached to main Show by diagram relation of lateral | to wall of building served. | | |
| o A saud | TV ac//-Pike | | |
| passed by the City Council, and Rule. | Into a seek to be a | | |
| 1 0+ 0 | Landon St. | | |
| Signed TV . J. B. A. | Filed at Engineer's Office AUG 18192 | | |

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

| | FERN | ALL IC |) IAP | SEWE |
|-----------------------------------|---|----------------|--|----------------|
| | itsəci bar 176 5 e 11765 olendəri | | | Lherotrani -31 |
| | | | | 19 |
| Received of A | | Good . | | fee_of \$ |
| for which permission is granted | 91. | | | |
| for which permission is granted. | | | | |
| to tap Many | | ewer, on the | | |
| of Taylor | LIV LIDVED FYMILE | Ave., Type | A STATE OF S | dish |
| | | | | . |
| the premises being Lot. No. | 4621 | Ho | use No | /57 |
| Work to be done in accordance v | with Ordinance 1 | No. 2323, duly | passed by the | City Council, |
| the Department of Public Service. | | | | |
| | //_ | | | |
| Name of Contractor 423 | | 2.0 | 化三角二多合物 化二氯异氰烷 | |

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.