FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED  $\mathbf{N}_{-}^{\mathbf{o}}$  2879 10 - 14Date Inspected Marc If so how and location from first manhole down stream\_\_ House No. /4/8 Distance from first manhole down stream to ditch at Size of pipe used # ... curb line and depth..... Was lateral at curb? M. L. Was attached to main. Show by diagram relation of lateral to wall of building served. Litabull lo say T yes All Mills done in accordance with Ordinance No. 2321, duly passed by the City Council, and Rules of

## Nº 2879

## PERMIT TO TAP SEWER

cation from	to both frequency of the condition of the condition and to
	Massillon, O.,19
Received of	Constant fee of 8 2 5
for which permission is granted	Jews Bruken ing hayan si Vi
Landon	(Mail to sulphi East Modernie and
of Roy-post X	Sewer, on the Ave., Type of Street
the premises being Lot. No.	St. 1418 House No. 728
	h Ordinance No. 2323, duly passed by the City Council, and Ru

the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of buil is subject to Massillon Board of Health Regulations.