## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR NO. 2882 AND SIGNED WHEN RETURNED SOS

Date Inspected Afra	il 6 If so how	and location from		
House No. 328		nole down stream		
Size of pipe used 6 1	down stre	from first manhole am to ditch at	o bayesii	
		and depth	0 0	
Was attached to main	with Hub Name of	Contractor Frank	ilm & Car	ly.
	n of lateral to wall of building s	。" [1] 17 · 18 · 18 · 19 · 19 · 19 · 19 · 19 · 19		

Was attached to main with that Name of Contractor translating & Barly

Show by diagram relation of lateral to wall of building served.

Show by diagram relation of lateral to wall of building served.

ON 1993 10 997 1 994

ON 1993 10 998 10 9

Signed A - H. Boyd Erile St. APR9

Remarks Sateral connected to main with thich 3 ft from Strain line on House

Nº 288

## PERMIT TO TAP SEWER

ing the state of t	ireact bus was or it is	4	Sylvania in the comment
( personny	Jewohi olosingsi isali (	Massillon, O.,	<b>2</b> – 192.
Land for		$\mathcal{I}_{i}$	22
Received of	The Jose Sale Gills J	///	fee of \$
for which permission is granted	trank	Lung H Cally	A second restre
그 그림 선생님 그는 경기를 다 되는 생산 중에 가는 끝들이 되었다.	in in the contract of		1 40
to tap Stone	sewer,	on the	And the second s
9		is satisfy the appropriate and dayledness	
of Child	A St	ve., Type of Street	prime of
	7.5 2	House No.	728
the premises being Lot. No	<b>★</b> ***	House No	

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule the Department of Public Service.

the Department of Fublic Service.

NOTE. This permit covers work outside of building only. Any work inside walls of buil is subject to Massillon Board of Health Regulations.