FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 2896Date Inspected March If so how and location from

first manhole down stream. House No. 1092 Distance from first manhole down stream to ditch at Size of pipe used bom

curb line and depth...

Was lateral at curb?

Was attached to main.....

- with Ordinance No. 2323, duly pussed by the City Council, and Regardiff

Show by diagram relation of lateral to wall of building served.

Name of Contractor.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

2896Massillon, O. for which permission is granted the premises being Lot. No

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule the Department of Public Service.

Name of Contractor Lan Louis

NOTE. This permit covers work outside of building only. Any work inside walls of built is subject to Massillon Board of Health Regulations.