

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 2912

Date Inspected April 5

If so how and location from
first manhole down stream

House No. 1134

Distance from first manhole
down stream to ditch at
curb line and depth


Size of pipe used 6 in

Was lateral at curb? yes

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.



Signed A. T. Boyd

Inspector for City

Filed at Engineer's Office

APR 6 19

Remarks Lateral connected to lateral at curb 14 ft from Strai

line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No 2912

PERMIT TO TAP SEWER

Massillon, O., April 4th 1922

Received of T. G. [Signature] fee of \$ 2.00

for which permission is granted P. E. [Signature]

to tap [Signature] sewer, on the [Signature]

of [Signature] Ave., Type of Street driv
3rd ST SE St.

the premises being Lot: No. 4214 8201 House No. 1134

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule
the Department of Public Service.

Name of Contractor P. E. [Signature]

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.