

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 2960

Date Inspected May 23

If so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at

Size of pipe used _____

curb line and depth

Was lateral at curb? _____

Name of Contractor Jes Bunker

Was attached to main _____

Show by diagram relation of lateral to wall of building served.

Signed A. J. Boyd Inspector for City

Filed at Engineer's Office. MAY 26 192

Remarks: lateral put on main with Hub 24 ft long on strait line with man hole

NO. 2960

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Massillon, O., May 21 1919

Received of John Brunker Fee of \$2.00

for which permission is granted

to tap San sewer, on the

of Karrison Ave. NE Ave., Type of Street

the premises being Lot No. 3545, House No. Van Cl

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rules of the Department of Public Service.

Name of Contractor Brunker

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.