FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected func 13	I so how and location from first manhole down stream	
House No. 2524	Distance from first manhole down stream to ditch at	
Size of pipe used A ma	down stream to ditch at curb line and depth	
Was lateral at curb?	Name of Contractor Translin & Barly	
Was attached to main		
Show by diagram relation of lateral t		
haan tirk ii biis kaan kista tulkiin liha kista ka kista ka ka		
House No.		
	all sales 30 Holike	
Rouse No.	1888 LOW SERBORIES OF THE STATE OF THE SERBORIES OF THE S	
Rouse No.	See an espanial intersonairone y mobad is sow	1.

Nº 2969

\mathbf{N}^{c} 2969

PERMIT TO TAP SEWER

meri notracelina wod os merski neob stodana jej N	Massillon, O., May 3/2
Received of Organization	fee of \$2
for which permission is granted. 720	Mintearly
to tap fantary sew	are the second s
tara mala di kacambangkatan katangga and ang Papatan tahun kacamanan panan di dikabahang paganggangga Katang di 🛣 🛣 🕬 🛣 🛣 🛣 🛣 🛣 🛣 🔻 🕏 🔻 🕳 🕳 🕳 🕳 🕳 🕳 🕳 🕳 🕳 🕳 🕳 🕳 🕳	THE RELEGIOUS CONTROL OF AN ARM AND A CONTROL OF THE ARM AND A CONTROL OF A CONTROL
of Kym We Alt.	Ave., Type of Street. A. A. St.,
the premises being Lot No. 50/4	, House No
Work to be done in accordance with Ordinance N	o. 2323, duly passed by the City Council, and
the Department of Public Service.	
Name of Contractor	arly .
	le of building only. Any work inside walls o

is subject to Massillon Board of Health Regulations.