FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 3055	AND SIGNED WHEN RETURNED	6-51
Date Inspected	I so how and location from first manhole down stream	
House No.	Distance from first manhole down stream to ditch at	
Size of pipe used	curb line and depth.	
Was lateral at curb?	트로워보겠고 스트스 트로워 발표 Electronia 한 분들은 하는 트로스 트로워 보다는 이 보냈다. 그는 보내는 보내는 사람들은 그는 그는 그는 그를 모르는 것이 되었다. 그는 그는 그는 그는 그	
Was attached to ma	Name of Contractor	V -> <
Show by diagram rel	ation of lateral to wall of building served.	
Aur. See to Emily one	# 3 Mattitue 50 0 0 - 50 / 131 - 51/2 - 100 5 / 7	
Signed	MACE MACH Filed at Engineer's Office SEP 1 / 1928	
	Inspector for City	

No

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N_{c} 3	055	PER	MIT T	O TA	P SEW	ER
	inari sel		Massill	on, O.,	447	L
Receive	d of		/	<u></u>	fee of	\$ <u>2</u>
for which peri	nission is granted	digula lice/sint y L	$2. \Omega$	mula	4	eraica Activa
to tap	anta	usi Isnalisa sin La La Santa sa sin	ewer, on the		1.5-1.76	
of 2 an	ul.	110	Ave., T	ype of Street.	e indicate de la companya de la comp	-1-1
the premises b	eing Lot No.	21 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3) St.,		846	
	ne in accordance	with Ordinance				il, and
the Departme	nt of Public Serv	ice.	1			
Name of Cont	ractor	(//	Krs.			

NOTE. This permit covers work outside of building only. Any work inside walls of bu

is subject to Massillon Board of Health Regulations.