FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 7 - 32

| Date Inspected OCA-5 | I so how and location from |
|---|--|
| House No. 326 | first manhole down stream |
| Size of pipe used | down stream to ditch at the strength of the st |
| Was lateral at curb? | Name of Contractor Geo Carly |
| Was attached to main | Table of Contractor |
| Show by diagram relation of lateral to wa | all of building served. House |

 $N_{\cdot}^{\circ} = 3071$

Signed A F Band Filed at Engineer's Office. OCT

Remarks: Saleral connected to lateral at curb & & from a

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3071 PERMIT TO TAP SEWER

| | igenijan ireny Nova: diremi | ien woo en I slaannistisii | Massillon, O. | 14 | 124 | 19 |
|----------------------|--------------------------------|--|--|----------------|-----------------|----------|
| Received of. | Langueta | G_{0} | | * | fee of \$ | <i>ب</i> |
| for which permission | n is granted | Harry Commission of the Commis | | | 4 | |
| to tap | Ling. | , | r, on the | | <u> </u> | |
| of 21. | <u> </u> | 4.4. | Ave., Type of | Street | dit | |
| the premises being I | ot No. <i>G. G</i> | 04-66 | 가게 뭐 많아 가 하네 하고 뭐 다 | e No∽ | 6 | |
| Work to be done in | accordance with | h Ordinance No | . 2328, duly pa | ssed by the Ci | ty Council, and | Rτ |
| the Department of | Public Service. | | 1 | | | |
| Name of Contractor | اسرار کرا | | <u>-K) </u> | | | |

NOTE. This permit covers work outside of building only. Any work inside walls of buils subject to Massillon Board of Health Regulations.