

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

6-25

No. 3076

Date Inspected Oct 4

I so how and location from
first manhole down stream

House No. _____

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used 4 in


Was lateral at curb? yes

Name of Contractor

Franklin & Early

Was attached to main _____

Show by diagram relation of lateral to wall of building served.



6 1/2

82 ft Pipe

9

Main Sewer East ←

McKinley and S.W. ← Man Hole

Signed A. T. Boyd

Inspector for City

Filed at Engineer's Office

Remarks:

Lateral connected to lateral at curb 9 ft from Main

OCT 5

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3076

PERMIT TO TAP SEWER

Massillon, O., Oct 10th 1921

Received of Franklin & Early fee of \$ 2.00

for which permission is granted Franklin & Early

to tap sanitary sewer, on the sewer

of W. Pendleton Ave. Ave., Type of Street Driv.
St.,

the premises being Lot No. 44100, House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor Franklin & Early

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.