	FOLLOWING DATA TO BE ANSWERED BY INSPECTOR	سما
∴N? ∴3081 — ౖ	AND SIGNED WHEN RETURNED	
Date Inspecte Det 4/	28 I so how and location from first-manhole down stream	
House No	Distance from first manhole down stream to ditch at	
Was lateral at curb?	curb line and depth	
Was attached to main	at unit had it is a second because	
Show by diagram relation of later	al to wall of boulding served. South Side of House	
the classes with the casts on		-
Fact to	3 9 M.H. Seriored eliding Tournemproper entre OCT 8	1928
Signed Inspect	or for City	IDZ(
Remarks:	🖊 mangingsig musik 16 maga kanggang 6 mangasa	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3081

PERMIT TO TAP SEWÉR

	Massillon, O., Jeffer 29 19
Received of Advanced	Mailly fee of \$22
for which permission is granted	OB P Backery
to tap 12	nino amount sewer, on the factorial
of 100 - 100	11 1 Mer of the state of Street dust and St., St.,
나타를 사용하는 하는 사람들이 모든 살로 하지만 살살 때 살을 받는 것이 없다.	5c., 4-2-2-7 House No.
	th Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.	
Name of Contractor	13. 13. H

NOTE. This permit covers work outside of building only. Any work inside walls of building only. Any work inside walls of building only.