## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Oct //	I so how and location from
House No. 248	Distance from first manhole
Size of pipe used 6	down stream to ditch at curb line and depth.
Was lateral at curb? 1/0	$\Lambda$ is a constant $\Lambda$
Was attached to main with &	adel Name of Contractor ges Busker
and the second of the second o	
Show by diagram relation of laters	al to wall of building served. House
Show by diagram relation of laters	al to wall of building served.
Show by diagram relation of laters	7 U-P.Z.
Show by diagram relation of laters	7 U-P.Z.
Snow by diagram relation of laters	7 Ho H-OTE
Show by diagram relation of laters	The state of the s
Show by diagram relation of laters	7 Ho H-OTE

 $N_{0} - 3088$ 

## PERMIT TO TAP SEWER

	l so bow and location fro frat madhole down stres	Massillon, O.,	15 - 2/ - 19
Received of	J. Bus	he.	fee of \$==
	ranted ELCo		
大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大大	sewi	主义、自然中央企业的原则 化加州水平均均 化二氯化二氯化氯化化物物	Successor a free and the control of the first of the firs
of Faclory	PanNE	Ave., Type of Street St.,	Justi
the premises being Lot N	10 pt 27	House No	148
Work to be done in acco	rdance with Ordinance N	o. 2328, duly passed by	y the City Council, and Ru
the Department of Publ	· _ ·		

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.