

✓

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3091

Date Inspected Oct-15 I so how and location from
first manhole down stream.....

House No. 15 + 19 Distance from first manhole
down stream to ditch at
Size of pipe used 6 in curb line and depth.....


Was lateral at curb? yes

Was attached to main.....

Show by diagram relation of lateral to wall of building served.

Name of Contractor

Franklin & Early



22 ft Pipe

8 Main sewer south

5th St N. E

Signed

A. T. Boyd

Inspector for City

Filed at Engineer's Office

OCT 18 1911

Remarks:

lateral connected to main with saddle 32 ft from stream
line on House

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3091

PERMIT TO TAP SEWER

Massillon, O., Oct 12 1919

Received of _____ fee of \$ 2.00

for which permission is granted The Massillon Company

to tap _____ sewer, on the _____

of 5th St. E. Ave., Type of Street _____
St.,

the premises being Lot No. Pt 59, House No. 15 + 19

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.

Name of Contractor Franklin & Early

NOTE. This permit covers work outside of building only. Any work inside walls of bu
is subject to Massillon Board of Health Regulations.