FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected April 8	I so how and location from first manhole down stream	
House No. 709	Distance from first manhole	
Size of pipe used 6.m~	down stream to ditch at curb line and depth	
Was lateral at curb?	- A WH	
Was attached to main	Name of Contractor A William	
	- 1986年 (1986年 - 1987年) - 1986年	무늬 사람들은 사람들이 하나 하는 것
Show by diagram relation of late	eral to wall of building served. Houde	
Show by diagram relation of late	그리는 사람들이 되었다. 그는 그리고 함께 얼마나는 아무리를 하고 있다는 것이 되었다는 것이 되었다.	
	그리는 사람들이 되었다. 그는 그리고 함께 얼마나는 아무리를 하고 있다는 것이 되었다는 것이 되었다.	
na pi diree	20 M-Pipe	
e di chees	15 20 Min Pife 10 10 20 Min Pife 10 10 10 20 Find of the Vi	
na pi diree	20 M-Pipe	APR 9

No 3180

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 \mathbf{N}^{o} 3189

PERMIT TO TAP SEWER

	maria dellegel lesa viole de la Massillon, O., Clara y 19
1	Received of Annual Received of Annual Received of Received of Annual Received Received of Received of Received of Received Received of Received of Received of Received Received Received of Received of Received Received Received Received of Received Receiv
Ĩ	for which permission is granted.
	to tap sewer, on the sewer, on the sewer of
	of Street St., the premises being Lot No. 127, House No. 707
	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
	the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of built is subject to Massillon Board of Health Regulations.