FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N? 3208

Date Inspected 4/30/	I so how and location from 1941	
House No. $$	Distance from first manhole	
Size of pine used	down stream to ditch at	
Size of pipe used6	curb line and depth Geer	
Was lateral at curb?	() for a second of the property of	
	Name of Contractor 2 b Muffle Vach	
Was attached to main	The state of the s	
how by diagram relation of la	ateral to wall of building served.	e nakan pes
		No. 179 (1964) Stanford Processing
in Single Park Bull Library in a		
	Haran and the second second of the second second of the second second second second second second second second	
	1	
e distino villi M.H. d hizzasa	vim 1888 av seakairi siin maanain a Gairai oli inii	
	194 feet. /_	
		.
1 51	M	inv 1 1929
Signed	Filed at Engineer's Office.	HII
Inst	pector for City	
eran sid / Associate Mis	harden in the transfer of the contract of the	
Remarks:		

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3208

PERMIT TO TAP SEWER

Received of Caring and A	يالار
to tap	<u></u>
이렇게 하는 아니는 사람들이 아이들의 아이들의 아이들의 아이들의 아이들의 아이들의 아이들의 사람들이 되었다는 사람들이 하는 사람들이 되었다. 사람들이 아니는 아니는 사람들이 아니는 사	<u></u>
of Management of	
the premises being Lot No. 7372 , House No. 4//0	
Work to be done in accordance with Ordinance No. 2328, duly passed by the City Council,	and Ru
the Department of Public Service. Name of Contractor Road & Reddy L.	

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.