FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected July 5	I so how and location from
	first manhole down stream
House No. 30 7/	Distance from first manhole
하지 않는 그리다 아내는 그 말을 가야 하고 그리고 하는 사람들은 사람들은	down stream to ditch at
Size of pipe used &	curb line and depth
Was lateral at curb?	Name of Contractor Als Brunker
Was attached to main	to wall of building served.
	Main beyor barren our Main beyor barren our
. A. T. Bara	e Lincoln Way N. 91 Filed at Engineer's Office. JUL 1.1 rected to lateral st Main 90 ft from Ma Hol
Signed/! Inspector	for City JUL 11
Remarks: Stateral Com	rected to lateral st main 90 ft from Ma
	Hal

 $M_{
m o}$

-3270

 N° 3270

PERMIT TO TAP SEWER

o man. The state of the state o	áltsvál had svád az "Ís. A vodu division desil	Massillon, O.,	W 3 7 1
Received of	2 Run	maken ($\sqrt{\frac{0}{\text{fee of }}}$
	idan berteit in	Jan Sta	-L-L
for which permission is gran	Large		I - Sh
to tap		on the	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
of An Col-Table	7 ()	Ave., Type of Street. St.,	
the premises being Lot No	7547	, House No	307/
Work to be done in accordan	ce with Ordinance No.	2323, duly passed by	the City Council, and Ru
the Department of Public Se	ervice.		[2] 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Name of Contractor	3 (13 mm		

is subject to Massillon Board of Health Regulations.

This permit covers work outside of building only. Any work inside walls of bu