FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED 1.3277

1	마음 등록 경험을 통해 통해 경험을 받는 것을 받는 것이 되었다. 그는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없는 것이 없다.
Date Inspected Mills 10	I so how and location from first manhole down stream
House No. 37/	Distance from first manhole
Size of pipe used 4 An	down stream to ditch at curb line and depth.
Was lateral at curb?	
Was attached to main.	Name of Contractor Dan Hranklin
Show by diagram relation of laters	al to wall of building served.
	1 / 47 ft hipe
	The first series supplied $T_{ij}(f)$
biro (linea)) validedi va lessasi vlat	. USE LV squame of area sometrans at another Local Section
	Man Believe Worth
4 01 0	94 AL IL OIL
Signed T. T. Bayya	Filed at Engineer's Office JUL 1-1
Inspecto	or for City

N^c 3277

PERMIT TO TAP SEWER

inical deliberations workers. Massellon O. W. B. H.
Received of Caudinandum Massillon, O., Hope of \$2
for which permission is granted Sam— Franklin
to tan Manutany sewer, on the west
of 27 4 4 4 M. Ave., Type of Street. air
the premises being Lot No. 4/1-4/16, House No. 37/
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.
Name of Contractor, San Franklin

NOTE. This permit covers work outside of building only. Any work inside walls of building to Massillon Board of Health Regulations.