FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

7 - 33

AND SIGNED WHEN RETURNED

Date Inspected	94	T 1				
Date Inspected/1/2		I so how and loc first manhole do	がき こうさん しゅうしょ しきいしょう			
House No. 233	6 Williams	i prima a cina a prima d	함께 가는 것이 없는데 그는데 그 없다.			
House Ivo.		Distance from fir	化二氯甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基甲基			
Size of pipe used,	6 m	down stream to d curb line and dep		. beviese/i		
		curo ime anu uep				
Was lateral at curl	b?~120				7 42	
		Name of Contract	or 1920	Oasl	v	
Was attached to a	main			and the second	-	

Show by diagram relation of lateral to wall of building served.

Nº 3294

diversal solution of the solut

Filed at Engineer's Office JUL 2:

Remarks: Lateral Commented to Paternel at curt & ft from Str

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 N^c 3294

PERMIT TO TAP SEWER

neni.	Nilesai kiik vaita Nily vininnin	Massillon, O.,	D-17 Ed
Received of		and the	fee of \$
r which permission is gra	nted	1 Les et Eles	
tap		sewer, on the	erit (i
Man	180-6 M	Ave., Type of Street St.,	11/2/7
e premises being Lot No.	3755	House No	2336
ork to be done in accorda	ance with Ordinanc	e No. 2323, duly passed by t	he City Council, and
e Department of Public	Service.		
at Contractor	in los	a da -	

NOTE. This permit covers work outside of building only. Any work inside walls of building to Massillon Board of Health Regulations.