

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 3302

Date Inspected July 24

I so how and location from
first manhole down stream

House No. 23

Distance from first manhole
down stream to ditch at

Size of pipe used 6 in

curb line and depth

Was lateral at curb? yes.

Name of Contractor

Was attached to main

Show by diagram relation of lateral to wall of building served.

Free Brunner
14th St N.W.



43 ft-pipe

Signed

A. F. Bond

Inspector for City

Filed at Engineer's Office

Man Holes ☒ Main sewer in at

JUL 29 1917

Remarks:

Lateral connected to lateral in alley 3 ft from Man
Hole

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3302

PERMIT TO TAP SEWER

Massillon, O., July 22, 1919

Received of Howard B. Brunk fee of \$ 2.00

for which permission is granted Howard B. Brunk

to tap Sanitary sewer, on the South

of 74th St. NW Ave., Type of Street Dist.
St.,

the premises being Lot No. _____, House No. 23

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor Yes Brunk

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.