## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

N? _3359	AND SIGNED WHEN RETURNED
Date Inspected	I so how and location from first manhole down stream
House No. 2/69 Size of pipe used 6 200	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	사진 보고 가능성 등을 하지 않는 경에 그렇게 그렇게 되었다. 아이들 아이들 이 사람들이 그렇게 되었다면 하고 있다. 나는 그리고 얼마를 하는 것이다.
Was attached to main Show by diagram relation of lateral	
Hones Nil.	
I bio dionogoviil sis nd bestan vlute	LEES TO Summit to the estimation of summer of the summer o
Signed A. T. Brust	Filed at Engineer's Office. SEP 1-4-1
が動 かとうにとき着きにはことに関けていた。他には、2017年に、これにはその過じたらうとのは、2017年の日本芸術の代表に	ected to Man Hole Culing and Lank in rear

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 $N_0^{\circ}$  3359

## PERMIT TO TAP SEWER

	ingi nalisalka kata a katan	resident Mar	ssillon, O.,	1 1/4 19
Received of	re Copia Sit area  Attraction	Bick	$\mathcal{L}_{i}$	fee of \$
for which permission		2	and the second	~
to tap	10-7	sewer, on	the	Labara (2007) Hall (18) Second Carlotter (2008) 18
of	-10 m/	ِ کےAve. St.,	. Type of Street	- 12a-c
the premises being Lo	ot No5	340	, House No	2109
Work to be done in a	ccordance with Or	dinance No. 232	3, duly passed by t	he City Council, and Ru
the Department of P	ublic Service.	0		
Name of Contractor	Os il	·		in termina

NOTE. This permit covers work outside of building only. Any work inside walls of building to Massillon Board of Health Regulations.