FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected 24 18	I so how and location from first manhole down stream
House No. 2207	Distance from first manhole down stream to ditch at
Size of pipe used $4m$	curb line and depth
Was lateral at curb? 22 ld	Maring de/
Was attached to main	Name of Contractor om Aucting
Show by diagram relation of lateral to v	wall of building served. Hands 16/2
ve. Type of Street.	\prime . The second contribution is \prime
ils Overoit	78 H fife
Dons Remork vill) off will headinglob (82%)	8. ioU wansaihiO diku wandinguw ni sahib ed at Ariji Wasa Sewer West
A H B. 1	Sincoln Way E
Signed A J D My C	Filed at Engineer's Office // SEP 27-12
Inspector for	Tod to lateral al Marin 31 1/ trom Me

Nº 3376

 \mathbf{N}^{c} 3376

PERMIT TO TAP SEWER

	es kow cad bestion from	Massillon, O.,	16 17th 19
Received of	inayy Yorkan (leeves 1	fee of \$
for which permission i	s granted	Thomas Home	a auntre
to tapl		VI wer, on the	760 V
of Aced	willing E.	Ave., Type of StreetSt.,	brick
the premises being Lot	No. 3344	House No	2207
Work to be done in ac	cordance with Ordinance l	No. 2323, duly passed by the	e City Council, and Ru

the Department of Public Service.

Name of Contractor to - Curta

NOTE. This permit covers work outside of building only. Any work inside walls of building to Massillon Board of Health Regulations.