FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Left 18	I so how and location from first manhole down stream
House No. 26/7	Distance from first manhole down stream to ditch at
Size of pipe used 6 202. Was lateral at curb? 27 122	curb line and depth
Was attached to main	Name of Contractor Lan Franklin
Show by diagram relation of lateral to	wall of building served. House
A Demonstration	12 01/ 20 Man of she 32/ of Main Dewer East
its, doir reseat by the City Council, and	12 .01/ 2011 Man Hal 32 of Main Dewer East
	Jan to San Man 1/91/
Signed A Inspector for	filed at Engineer's Office SEP 27 192
Signed Inspector for Remarks Advisor Connection	nected to Interal al main 4 ft from No

Note that N_{2}^{max} and N_{2}^{max}

PERMIT TO TAP SEWER

riori mutanol implyod os made un angle dodunati in	Massillon, O.,	ne je grad a je 19
Received of Andrews	Parzur	
for which permission is granted	Frankl	
to tap dendary sew	ver, on the	24-24b
of in May AM	ics of leasth to serialer a Ave., Type of Street	park
the premises being Lot No. 8672	St., House No.	2617
Work to be done in accordance with Ordinance N	lo. 2323, duly passed by the	e City Council, and Ru
the Department of Public Service.	10	
Name of Contractor A G		

NOTE. This permit covers work outside of building only. Any work inside walls of bu

is subject to Massillon Board of Health Regulations.