## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

line on Hou

Date Inspected Och 18	I so how and location from first manhole down stream
House No. 437	Distance from first manhole down stream to ditch at
Size of pipe used A	curb line and depth
Was lateral at curb? 1900	Name of Contractor Sam Frankish
Was attached to main	to wall of huilding served // had 15
testic to agrif	to wall of building served.
	Celler drain
Of hair decire hyddredd yr dienesig yllab.	and on anaramary that sourminous in subject of an side.
	Mann Dewer Worth >
Signed A. F. Boys	6 97 th St W. W OCT 21 Filed at Engineer's Office.
Inspector Remarks:	for City rected to lateral at curb 12/2 // from DI

 $N_{\odot}^{\circ} = 3398$ 

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

egyrt golfabbi baz med gy etcyf b gwab wlodgwig igi	Massillon, O., 2 1.17 19
Received of Am Tari	fee of \$ 24
for which permission is granted 6	Dchory
to tap sev	ver, on theAve., Type of StreetAve.
the premises being Lot No. 4407	St., House No. 437
Work to be done in accordance with Ordinance N	No. 2323, duly passed by the City Council, and Ru
the Department of Public Service.  Name of Contractor	<u>M.</u>

3398

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.