FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected	I so how and location from first manhole down stream Distance from first manhole
Size of pipe used som	down stream to ditch atcurb line and depth
Was lateral at curb?	Name of Contractor Ger Contractor Ger Contractor
Was attached to main	
Show by diagram relation of lateral	is sold sold southern gufffife
dviy czased by the City Council, a	i ya manana ni yanana ingana angana angana ni wasa si yi ni anang sa wasa wasa wasan wasan ni ya sa kasan ka angan ni ya ya na angan ni ya ya na angan ni ya

- Nº - 3408

\mathbf{N}^{o} 3408

PERMIT TO TAP SEWÉR

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

	z end location from Dele deventeream	Massillo Massillo	n, O., <i>/// 4/1</i> /	
Received o	f	7.22-2-1.	a Ella,	fee of \$
for which permiss	on is granted	erif droo سستگست ومرس ومکس		in bom 10 Sunt
	Tenneth trad		$-\sqrt{t}$	Zen
	2. 1 1	Ave., Ty	gai ga a no salaa wa	4.7
01		419869888 K M #1988		
\sim \the premises being	Lot No. 8_2_2_2		House No	<i>[[]</i>
Work to be done i	n accordance with Ordi	nance No. 2323, du	ly passed by the (City Council, an
the Department of	Public-Service.			
Name of Contract	or_Elex.L	7 4		
	강렬한 입향 경험하다는 목숨을 살길 반속하다 내는 이 양성의 유경성은 상하는 기본 원생님이 문학되었다.		and the second section of the second second section in the second second second section is a second	