FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected Dec /2	I so how and location from first manhole down stream.
House No. 1234	Distance from first manhole
Size of pipe used 6 m	down stream to ditch at curb line and depth
Was lateral at curb?	<u></u>
	Name of Contractor A H Halcker
Was attached to main.	at to wall of hulding served $\mathcal{L}_{t_{n}}$, $\mathcal{D}_{t_{n}}$
Was attached to main	
	al to wall of building served. House
Show by diagram relation of latera	al to wall of building served.
Show by diagram relation of latera tended to envi-	al to wall of building served. 6'A to I naied at image and
Show by diagram relation of latera tended to envi-	al to wall of building served. (A foll gried ex) image of 1
Show by diagram relation of latera	al to wall of building served. 64 to I guide at image on 625 of tones; Carlin angabasang at samp of at Arov

Nº 3438

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 N_c° 3438

PERMIT TO TAP SEWER

	mori inizani kas wad or mori inizani kasa wad or	Massillon, O.	<u> </u>		
	Received of	Wards.	fee of \$ 2		
172-	for which permission is granted	Bitter or only			
		ewer, on the	<u> </u>		
	of person due 8.7	Ave., Type of Street	parea		
	the premises being Lot No.	, House No	/73/		
	Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru				
	the Department of Public Service.	/ }			
	Name of Contractor 4 7 Will A	7	A ASOLITION OF THE PROPERTY OF		

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.