

Wear
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

No. 3449

47205
Date Inspected

2/20/30

I so how and location from
first manhole down stream

House No.

11

Distance from first manhole
down stream to ditch at
curb line and depth

Size of pipe used

6

Was lateral at curb?

Yes


Was attached to main

Yes

Name of Contractor

Geo Carley

Show by diagram relation of lateral to wall of building served.



Signed

Frank B. Jones

Inspector for City

Filed at Engineer's Office

Sanitary
milk

2/24

Remarks:

Ear

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

No. 3449

PERMIT TO TAP SEWER

Massillon, O.,

1914

Received of

fee of \$ 2.00

for which permission is granted

to tap

sewer, on the

of

Ave., Type of Street

St.,

the premises being Lot No.

House No.

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Rule No. 1, of the Department of Public Service.

Name of Contractor

NOTE. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.