FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED Date Inspected I so how and location from first manhole down stream. Distance from first manhole down stream to ditch at Size of pipe used. curb line and depth..... Was lateral at curb?___ Name of Contractor Was attached to main Sanitary Connections Show by diagram relation of lateral to wall of building served. or consideration that the teach that the law for the City Council and Mulic St. coaling our energy of though Service. Signed Inspector for Gity

Remarks:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 3472

PERMIT TO TAP SEWER

nioù netineol dan wed es a sus preis plopissia ser	Massillon, O.,
and the facility of the control of t	Led fee of \$ 200
	m Mranklin
to tap service	ver, on the See Assistance of the Ave., Type of Street
어떻게 되다면 하는 살이 하는 것으로 되면 보고 되는 나는 그 사람들이 되는 것은 사람들이 되었다. 이 없는 사람들이 되었다.	- ''' '' '' '' '' '' '' '' '' '' '' '' '
the premises being Lot No 1044	<u> </u>
Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru	
the Department of Public Service.	
Name of Contractor	melli.

NOTE. This permit covers work outside of building only. Any work inside walls of but is subject to Massillon Board of Health Regulations.