FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected April 29	. I so how and location from first manhole down stream
House No. 2952 Size of pipe used 6 m	Distance from first manhole down stream to ditch at curb line and depth
Was lateral at curb?	Name of Contractor Ald Brunker
Show by diagram relation of lateral to w	all of building served.
· P. Senie	
1931, duly passoi by the City Coursis, and	10/1 so assure () 1/21 v oscisto o Main 9 Delver dest € 0
Signed A H Boyd	Sin Way West Piled at Engineer's Office.
Inspector for C Remarks: Lateral connec	Filed at Engineer's Office. Ted to lateral at Side walk 83 ft from Man Hale
	Man Hale

Nº 3484

OTDEVENI VE GENERALL BE OF

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

	eneri gobiest bas vest na Lunsut symbolostana	Massillon, O.,	12 July 29 19
Received of.	etoli)za iera ra Beneret	Le	fee of \$_2
for which permission	$ \frac{1}{2} 1$	Warin	tack et d
to tap	Land sev	ver, on the	urrth
	L. Vorrise Monthlind To	MAve., Type of Street.	porte
	ot No. 0 Z 1 8 /		
	accordance with Ordinance 1		
the Department of	Public Service		

Name of Contractor 12 221

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.