## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Date Inspected 5/3/30 I so how and location from first manhole down stream House No. House not built Distance from first manhole down stream to ditch at Size of pipe used curb line and depth. Was lateral at curb? Yes1 F. Harcker Name of Contractor. Was attached to main..... Show by diagram relation of lateral to wall of building served. IST ST. NE. Filed at Engineer's Office Inspector for City

 $N_{\odot} = 3487$ 

Remarks:....

antoneki ya dereveya be iv

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

## Nº 3487 PERMIT TO TAP SEWER

mort nel			May Julia	19
Received of	Value (1000)	1.	fee of \$	200
for which permission is grante	a //_/			
to tap denter		er, on the		
of	378	Ave., Type of Stre St.,	et	1
the premises being Lot No.	2293		140 16	***** <b>*</b>
Work to be done in accordance	with Ordinance No	o. 2323, duly passed	by the City Council,	, and Ru
the Department of Public Serv	vice.			
Name of Contractor	Meech			
NOTE. This permit	covers work outside	of building only.	Any work inside wa	lls of bu

is subject to Massillon Board of Health Regulations.