FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

10 - 10

AND SIGNED WHEN RETURNED

Date Inspected I so how and location from first manhole down stream House No. Distance from first manhole down stream to ditch at Size of pipe used..... curb line and depth_____ Was lateral at curb?_________ Was attached to main Show by diagram relation of lateral to wall of building served. Filed at Engineer's Office Inspector for City

3518

Remarks

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Nº 3518

	aow and bearion from	Massillon,	o lune	2 md	19
Received of	Julis 21	littmann	<i>)</i> /	fee of \$ 2	<i>a</i> u
一门,"我们就是一个,我们就是一个,我们就是一个人。"	js granted	かくほん ぎょういうしゃ いいりゅう しゅり かない	e de transcriptor de la companya de	eregin în Esil.	
	nilary			ELminne W	
	lival mainia			Dist	
公共的 化流光性化 化氯化锌 化硫甲酰磺胺磺基	Lo Lear	아이스 소리를 하다 하는 것이 됐다.		3-0	
	it No.				э т о

Work to be done in accordance with Ordinance No. 2325, duly passed

the Department of Public Service.

Name of Contractor Julius Mulli,

NOTE. This bermit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.