FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

line on Hall

House No. 897	Distance from first manhole	in the state of th
Was lateral at curb? 19 (2) Was attached to main	Name of Contractor	reconstant
Show by diagram relation of latera	l to wall of building served.	LE House
· · · · · · · · · · · · · · · · · · ·		1 34 ft foife
d ing digued (Ary Council, and Calact		All alon ed at an average and the state of t
Signed A A Barrier Inspector	Add Filed at	St. O. A. JUL 819; Engineer's Office. JUL 819;

Nº 3529

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Nº 3529

Received of Street Massillon, O., Mes 27 19

Received of Street O. Street Massillon, O., Mes 27 19

Received of Street O. Street Massillon, O., Mes 27 19

Received of Street O. Street O. Street Street Str., House No. 837

Work to be done in accordance with Ordinance No. 2323, duly passed by the City Council, and Ru the Department of Public Service.

Name of Contractor 10 . Co

NOTE. This permit covers work outside of building only. Any work inside walls of bu is subject to Massillon Board of Health Regulations.